



Errata

NFPA 70®

National Electrical Code®

2014 Edition

Reference: Various
Errata No.: 70-14-3

The National Electrical Code Correlating Committee notes the following errors in the 2014 edition of NFPA 70, National Electrical Code.

- 1. 210.19(A), Informational Note No. 4. Change the reference in the last sentence to "Informational Note 2 of 215.2(A)(1)(b)."
2. Table 310.15(B)(3)(c). Revise second entry in the first column to read "Above roof 13 mm (1/2 in.)-90 mm (3 1/2 in.)."
3. 406.9(B)(1). Revise the first sentence by inserting ", 125 and 250 volts" after "amperes".
4. 409.1, Informational note. Change the reference to read: ANSI/UL 508A.
5. 600.33(A). Revise first sentence to read "Listed Class 2 cable that complies with Table 725.154..."
6. 690.12(4). Change the reference to 690.56(C)
7. 690.15(D). Delete entire section. This is a duplicate of 690.13(D)
8. 725.154(A). Revise first sentence as follows: The substitutions for Class 2 and Class 3 cables listed in Table 725.154(A) and illustrated in Figure 725.154(A) shall be permitted.
9. Add table as follows:

Table 725.154(A) Cable Substitutions

Table with 2 columns: Cable Type and Permitted Substitutions. Rows include CL3P, CL2P, CL3R, CL2R, PLTC, CL3, CL2, CL3X, and CL2X.

- 10. Table C.9(A) Change the third trade size from 1 3/4 to 3/4. Change the metric equivalent from (2) to (21).

Issue Date: April 21, 2014

(Note: Electronic products and pamphlet reprints may have this errata incorporated. For current information about the NFPA Codes and Standards, including this errata, please see www.nfpa.org/codelist)